

APPENDIX C

COMMENTS ON FCC TV ENGINEERING DATA BASE (MAY 13, 1996)

The following are forms that stations across the country have sent to the Broadcasters Caucus and are organized in two sets by region. The first set of forms identify errors or discrepancies in the FCC's database. The second set of forms confirm instances in which the FCC's database is correct. Stations continue to send in forms and the Caucus will continue to work with the Commission to verify and update the FCC Data Base.

APPENDIX C1

**PROPOSED CORRECTIONS TO
FCC TV ENGINEERING DATA BASE
(BY REGION)**

11/20/96

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VICTOR TAWIL

FROM: KFTY - ERIC PETER Region 1
Telephone: (707) 526-5050

RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

| | | Check Here if Correct |
|-----------------------|------------------------|--------------------------|
| Station Call Sign: | <u>KFTY</u> | <u>✓</u> |
| Channel: | <u>50</u> | <u>✓</u> |
| Power: | <u>398 KW - ERP</u> | <u>—</u> |
| Antenna Height: | <u>939 HAAT (M)</u> | <u>✓</u> |
| RCAMSL: | <u>1358 RCAMSL (M)</u> | <u>✓</u> |
| Transmitter Location: | | |
| Latitude: | <u>38-40-10</u> | <u>✓</u> |
| Longitude: | <u>122-37-52</u> | <u>✓</u> |
| Directional Antenna: | <u>RCA ODDTFU-25G</u> | <u>—</u> |
| Reference Angle: | <u>—</u> | <u>—</u> |

Please provide any necessary corrections in the spaces below:

| | |
|-----------------------|-----------------------|
| Station Call Sign: | <u>—</u> |
| Channel: | <u>—</u> |
| Power: | <u>302 KW - ERP</u> |
| Antenna Height: | <u>—</u> |
| RCAMSL: | <u>—</u> |
| Transmitter Location: | |
| Latitude: | <u>—</u> |
| Longitude: | <u>—</u> |
| Directional Antenna: | <u>RCA ODDTFU-25G</u> |
| Reference Angle: | <u>—</u> |

CA Region 1

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VIC TAWIL
 FROM: Norman Hall Region 1
 Telephone: 805 637-2323
 RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

Check Here
if Correct

| | | |
|-----------------------|-------------------------------------|-------------------------------------|
| Station Call Sign: | <u>KERO-TV</u> | <input checked="" type="checkbox"/> |
| Channel: | <u>23</u> | <input checked="" type="checkbox"/> |
| Power: | <u>1.76 or 1760</u> not <u>1780</u> | <input checked="" type="checkbox"/> |
| Antenna Height: | <u>1128</u> | <input checked="" type="checkbox"/> |
| RCAMSL: | <u>2323</u> | <input checked="" type="checkbox"/> |
| Transmitter Location: | | |
| Latitude: | <u>35-27-14</u> | <input checked="" type="checkbox"/> |
| Longitude: | <u>118-35-32</u> | <input checked="" type="checkbox"/> |
| Directional Antenna: | <u>GE 216-2AGTY96</u> | <input type="checkbox"/> |
| Reference Angle: | <u>?</u> | <input type="checkbox"/> |

Please provide any necessary corrections in the spaces below:

| | |
|-----------------------|-------|
| Station Call Sign: | _____ |
| Channel: | _____ |
| Power: | _____ |
| Antenna Height: | _____ |
| RCAMSL: | _____ |
| Transmitter Location: | |
| Latitude: | _____ |
| Longitude: | _____ |
| Directional Antenna: | _____ |
| Reference Angle: | _____ |

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VICTOR TAWIL

FROM: DALE KELLY, Region 1
Telephone: 209-453-8830

RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

**Check Here
if Correct**

Station Call Sign:
Channel:
Power:
Antenna Height:
RCAMSL:
Transmitter Location:
Latitude:
Longitude:
Directional Antenna:
Referente Angle:

KMPH-TV
26

11/17/19

Please provide any necessary corrections in the spaces below:

Station Call Sign:
Channel:
Power:
Antenna Height:
RCAMSL:
Transmitter Location:
Latitude:
Longitude:
Directional Antenna:
Reference Angle:

YES
270 DEC.

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: Victor Tawil

FROM: Rosa Maria Gendron, Region 1
Telephone: (209)48807440

RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

Check Here
if Correct

| | | |
|-----------------------|-------|-------|
| Station Call Sign: | _____ | _____ |
| Channel: | _____ | _____ |
| Power: | _____ | _____ |
| Antenna Height: | _____ | _____ |
| RCAMSL: | _____ | _____ |
| Transmitter Location: | _____ | _____ |
| Latitude: | _____ | _____ |
| Longitude: | _____ | _____ |
| Directional Antenna: | _____ | _____ |
| Reference Angle: | _____ | _____ |

Please provide any necessary corrections in the spaces below:

| | |
|-----------------------|---------------------|
| Station Call Sign: | <u>KNXT</u> |
| Channel: | <u>49</u> |
| Power: | <u>2150 kw</u> |
| Antenna Height: | <u>203'</u> |
| RCAMSL: | <u>5886' AMSZ</u> |
| Transmitter Location: | |
| Latitude: | <u>36° 17' 14"</u> |
| Longitude: | <u>118° 50' 17"</u> |
| Directional Antenna: | <u>yes</u> |
| Reference Angle: | <u>204° - 298°</u> |

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VICTOR TALLON
 FROM: KH12/Ray Crawford Region 1
 Telephone: 615-841-5654 x234
 RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

Check Here
if Correct

| | | |
|------------------------|-----------------------|-------------------------------------|
| Station Call Sign: | <u>KH12</u> | <input checked="" type="checkbox"/> |
| Channel: | <u>64</u> | <input checked="" type="checkbox"/> |
| Power: | <u>3160.0 ERP-KW</u> | <input checked="" type="checkbox"/> |
| Antenna Height: | <u>518.0</u> | <input checked="" type="checkbox"/> |
| RCAMSL: | <u>1424.0</u> | <input checked="" type="checkbox"/> |
| Transmitter Location: | | |
| Latitude: | <u>34-36-34</u> | <input checked="" type="checkbox"/> |
| Longitude: | <u>117-17-11</u> | <input checked="" type="checkbox"/> |
| * Directional Antenna: | <u>RCA 00070901K5</u> | <input checked="" type="checkbox"/> |
| Reference Angle: | <u>00</u> | <input checked="" type="checkbox"/> |

Please provide any necessary corrections in the spaces below:

| | |
|------------------------|------------------------------|
| Station Call Sign: | _____ |
| Channel: | _____ |
| Power: | _____ |
| Antenna Height: | _____ |
| RCAMSL: | _____ |
| Transmitter Location: | _____ |
| Latitude: | _____ |
| Longitude: | _____ |
| * Directional Antenna: | <u>DIELECTRIC TEL-363DAS</u> |
| Reference Angle: | _____ |

* NOTE: THIS ANTENNA MAY BE THE SAME ONE USING AN RCA PART #

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VICTOR TAWIL

FROM: BUD ALGER, Region 2
 Telephone: (206) 282-2202

RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

| | | Check Here if Correct |
|-----------------------|------------------|--------------------------|
| Station Call Sign: | <u>KTZZ-TV</u> | ✓ |
| Channel: | <u>22</u> | ✓ |
| Power: | <u>5000</u> | ✓ |
| Antenna Height: HAAT | <u>366</u> | — |
| RCAMSL: | <u>402</u> | — |
| Transmitter Location: | | |
| Latitude: | <u>47-36-57</u> | — |
| Longitude: | <u>122-18-26</u> | — |
| Directional Antenna: | | — |
| Reference Angle: | | — |

Please provide any necessary corrections in the spaces below:

| | |
|-----------------------|-----------------|
| Station Call Sign: | <u>KE</u> |
| Channel: | _____ |
| Power: | _____ |
| Antenna Height: HAAT | <u>271.27 M</u> |
| RCAMSL: | <u>319.73 M</u> |
| Transmitter Location: | |
| Latitude: | _____ |
| Longitude: | _____ |
| Directional Antenna: | _____ |
| Reference Angle: | _____ |

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VICTOR TAVIL
 FROM: GARY SMITH, Region 2
 Telephone: 208-522-5100
 Fax: 208-522-5103
 RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

| | | Check Here if Correct |
|-----------------------|--------------------|--------------------------|
| Station Call Sign: | <u>KIDK</u> | <u>✓</u> |
| Channel: | <u>3</u> | <u>✓</u> |
| Power: | <u>100 Kw ERP</u> | <u>✓</u> |
| Antenna Height: | <u>488 (m)</u> | <u>—</u> |
| RCAMSL: | <u>2054.00 (m)</u> | <u>—</u> |
| Transmitter Location: | | |
| Latitude: | <u>43-29-51</u> | <u>✓</u> |
| Longitude: | <u>112-39-50</u> | <u>✓</u> |
| Directional Antenna: | <u>—</u> | <u>—</u> |
| Reference Angle: | <u>—</u> | <u>—</u> |

Please provide any necessary corrections in the spaces below:

Station Call Sign:
 Channel:
 Power:
 Antenna Height: 493.47
 RCAMSL: 2048.86 (m)
 Transmitter Location:
 Latitude:
 Longitude:
 Directional Antenna:
 Reference Angle:

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VICTOR TAWIL

FROM: BRIAN LAY, Region 2
Telephone: 266 446-3831

RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

| | | Check Here if Correct |
|-----------------------|------------------|--------------------------|
| Station Call Sign: | <u>KONG-TV</u> | _____ |
| Channel: | <u>16</u> | _____ |
| Power: | <u>5000</u> | _____ |
| Antenna Height: | <u>389</u> | _____ |
| RCAMSL: | <u>514</u> | _____ |
| Transmitter Location: | | |
| Latitude: | <u>47 32 34</u> | _____ |
| Longitude: | <u>122 06 25</u> | _____ |
| Directional Antenna: | | _____ |
| Reference Angle: | | _____ |

Please provide any necessary corrections in the spaces below:

| | |
|-----------------------|------------------|
| Station Call Sign: | <u>KONG-TV</u> |
| Channel: | <u>16 MINUS</u> |
| Power: | <u>5000</u> |
| Antenna Height: | <u>279</u> |
| RCAMSL: | <u>239</u> |
| Transmitter Location: | |
| Latitude: | <u>47 37 55</u> |
| Longitude: | <u>122 20 59</u> |
| Directional Antenna: | |
| Reference Angle: | |

} (CHANGED)

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VICTOR TAWIL
FROM: BRIAN LAY, Region 2
Telephone: 206 448-3831
RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

Check Here
if Correct

| | | |
|-----------------------|------------------|-------|
| Station Call Sign: | <u>KING-TV</u> | _____ |
| Channel: | <u>5</u> | _____ |
| Power: | <u>100 kW</u> | _____ |
| Antenna Height: | <u>356 M</u> | _____ |
| RCAMSL: | <u>402 M</u> | _____ |
| Transmitter Location: | | |
| Latitude: | <u>47 37 55</u> | _____ |
| Longitude: | <u>122 28 59</u> | _____ |
| Directional Antenna: | <u>-</u> | _____ |
| Reference Angle: | <u>0</u> | _____ |

Please provide any necessary corrections in the spaces below:

| | |
|-----------------------|--------------|
| Station Call Sign: | _____ |
| Channel: | _____ |
| Power: | _____ |
| Antenna Height: | <u>250 m</u> |
| RCAMSL: | <u>296 m</u> |
| Transmitter Location: | |
| Latitude: | _____ |
| Longitude: | _____ |
| Directional Antenna: | _____ |
| Reference Angle: | _____ |

| | | | |
|------------------|---------------------|------|---------------------|
| Post-it Fax Note | 7671 | Date | # of pages <u>2</u> |
| To | <u>VICTOR TAWIL</u> | From | <u>BRIAN LAY</u> |
| Co./Dept. | | Co. | <u>KING-TV</u> |

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

3 PAGES TOTAL

TO:

VICTOR TAWIL

FROM:

KPDX, Region 2

Telephone: 503 872 9108 - ED WILLIAMS, C.E.

RE:

FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

Check Here
if Correct

Station Call Sign:

KPDX

✓

Channel:

49

✓

Power:

1450

✓

Antenna Height:

527

✓

RCAMSL:

616

✓

Transmitter Location:

Latitude:

45-31-22

✓

Longitude:

122-45-07

✓

Directional Antenna:

ADC 000941108KE

✓

Reference Angle:

0.0

✓

Please provide any necessary corrections in the spaces below:

Station Call Sign:

Channel:

Power:

* 3160.0 KW *

Antenna Height:

RCAMSL:

Transmitter Location:

Latitude:

Longitude:

Directional Antenna:

Reference Angle:

LICENSE COPY
ATTACHED

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: Victor Tawil
 FROM: Don Wilkinson, Region 2
 Telephone: (206) 443-4028

RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

| | | Check Here if Correct |
|-----------------------|------------------|--------------------------|
| Station Call Sign: | <u>KOMO-TV</u> | <u>✓</u> |
| Channel: | <u>4</u> | <u>✓</u> |
| Power: | <u>100 kw</u> | <u>✓</u> |
| Antenna Height: | <u>351 M.</u> | <u>—</u> |
| RCAMSL: | <u>398 M.</u> | <u>—</u> |
| Transmitter Location: | | |
| Latitude: | <u>47-37-56</u> | <u>✓</u> |
| Longitude: | <u>122-21-11</u> | <u>—</u> |
| Directional Antenna: | <u>NA</u> | <u>—</u> |
| Reference Angle: | <u>0</u> | <u>✓</u> |

Please provide any necessary corrections in the spaces below:

Present

Application filed 6/96

| | | |
|-----------------------|-----------------------------|------------------|
| Station Call Sign: | <u> </u> | |
| Channel: | <u> </u> | |
| Power: | <u> </u> | |
| Antenna Height: | <u>247 M.</u> | <u>225 M.</u> |
| RCAMSL: | <u>293 M.</u> | <u>322 M.</u> |
| Transmitter Location: | | |
| Latitude: | <u> </u> | |
| Longitude: | <u>122-21-10</u> | <u>122-21-11</u> |
| Directional Antenna: | <u> </u> | |
| Reference Angle: | <u> </u> | |

Don Wilkinson

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET


TO: VICTOR TAWIL
 FROM: Jim BOWEN, Region 2
 Telephone: 541 342-4961
 RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

| | | Check Here if Correct |
|-----------------------|------------------|-------------------------------------|
| Station Call Sign: | <u>KPIC</u> | <input checked="" type="checkbox"/> |
| Channel: | <u>4</u> | <input checked="" type="checkbox"/> |
| Power: | <u>5.4</u> | <input checked="" type="checkbox"/> |
| Antenna Height: | <u>305 M</u> | <input type="checkbox"/> |
| RCAMSL: | <u>506 M</u> | <input checked="" type="checkbox"/> |
| Transmitter Location: | | |
| Latitude: | <u>43 14 20</u> | <input type="checkbox"/> |
| Longitude: | <u>123 18 42</u> | <input type="checkbox"/> |
| Directional Antenna: | | <input type="checkbox"/> |
| Reference Angle: | | <input type="checkbox"/> |

Please provide any necessary corrections in the spaces below:

| | |
|-----------------------|-----------------------------|
| Station Call Sign: | <u> </u> |
| Channel: | <u> </u> |
| Power: | <u> </u> |
| Antenna Height: | <u>266 M</u> |
| RCAMSL: | <u> </u> |
| Transmitter Location: | |
| Latitude: | <u>43 14 08</u> |
| Longitude: | <u>123 19 17</u> |
| Directional Antenna: | <u> </u> |
| Reference Angle: | <u> </u> |

PER ADVISORY TO THE FCC, SEPTEMBER 18
 1997.


FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: Victor Tawil, MSTV

FROM: Don Perez, K*USA-TV, Region 3
Telephone: 303-871-1493

RE: FCC NTSC Engineering Database

Colorado

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

Check Here
if Correct

| | | |
|------------------------|---------------------|----------|
| Station Call Sign: | <u>K*USA-TV</u> | <u>x</u> |
| Channel: | <u>9</u> | <u>x</u> |
| Power: | <u>316 KW (ERP)</u> | <u>x</u> |
| Antenna Height: | <u>280 M (HAAT)</u> | <u>x</u> |
| RCAMSL: | <u>2,319 M</u> | <u>x</u> |
| Transmitter Location: | | |
| Latitude: | <u>39-43-46</u> | <u>x</u> |
| Longitude: | <u>105-14-08</u> | <u>x</u> |
| Directional Antenna: * | <u>no (Omni)</u> | <u>x</u> |
| Reference Angle: | <u>0</u> | <u>x</u> |

* Dielectric TW 12A9-R

Please provide any necessary corrections in the spaces below:

| | |
|-----------------------|-----------------------------|
| Station Call Sign: | <u>Same as Above</u> |
| Channel: | <u> </u> |
| Power: | <u> </u> |
| Antenna Height: | <u> </u> |
| RCAMSL: | <u> </u> |
| Transmitter Location: | |
| Latitude: | <u> </u> |
| Longitude: | <u> </u> |
| Directional Antenna: | <u> </u> |
| Reference Angle: | <u> </u> |

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: VICTOR TAWIL Region 3
 FROM: Rich Howe, Region 3
 Telephone: 520-778-6770 AZ - ARIZONA
 RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

| | | Check Here if Correct |
|-----------------------|-------------------------|--------------------------|
| Station Call Sign: | <u>KUSK</u> | ✓ |
| Channel: | <u>7</u> | ✓ |
| Power: | <u>9,600 watts ERP</u> | ✓ |
| Antenna Height: | <u>37 meters</u> | ✓ |
| RCAMSL: | <u>2,365 meters</u> | ✓ |
| Transmitter Location: | | |
| Latitude: | <u>34-42-17</u> | — |
| Longitude: | <u>112-06-55</u> | — |
| Directional Antenna: | <u>Omni-directional</u> | ✓ |
| Reference Angle: | <u>0°</u> | ✓ |

Old info on location. Should have been corrected 1987.

Please provide any necessary corrections in the spaces below:

Correct

| | |
|-----------------------|------------------|
| Station Call Sign: | _____ |
| Channel: | _____ |
| Power: | _____ |
| Antenna Height: | _____ |
| RCAMSL: | _____ |
| Transmitter Location: | |
| Latitude: | <u>34-41-15</u> |
| Longitude: | <u>112-07-01</u> |
| Directional Antenna: | _____ |
| Reference Angle: | _____ |

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: Television Station KRWG

FROM: Joe Snelson, Region 3, Technical Coordinator
Telephone: 913-677-7250

RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC Database is correct for your station.

Check Here
if Correct

| | | |
|-----------------------|------------|-------------------------------------|
| State: | NM | <input checked="" type="checkbox"/> |
| City of License: | LAS CRUCES | <input checked="" type="checkbox"/> |
| Station Call Sign: | KRWGTV | <input checked="" type="checkbox"/> |
| Channel: | 22 | <input checked="" type="checkbox"/> |
| Power: | 1550 KW | <input checked="" type="checkbox"/> |
| Antenna Height: | 137 mtr. | <input type="checkbox"/> |
| RCAMSL: | 1467 mtr. | <input type="checkbox"/> |
| Transmitter Location: | | <input type="checkbox"/> |
| Latitude: | 32 15 24 | <input checked="" type="checkbox"/> |
| Longitude: | 106 58 34 | <input checked="" type="checkbox"/> |
| Directional Antenna: | No | <input checked="" type="checkbox"/> |
| Reference Angle: | | <input type="checkbox"/> |

Please provide any necessary corrections in the spaces below:

| | |
|-----------------------|----------------|
| State: | |
| City of License: | |
| Station Call Sign: | |
| Channel: | |
| Power: | |
| Antenna Height: | 723 meters |
| RCAMSL: | 1,354.6 meters |
| Transmitter Location: | |
| Latitude: | |
| Longitude: | |
| Directional Antenna: | |
| Reference Angle: | |

PLEASE RETURN THIS FORM ONLY IF YOU HAVE CORRECTIONS BY FAX OR BY MAIL OR RESPOND VIA EMAIL NO LATER THAN OCTOBER 20, 1996 TO:

Victor Tawil
DTV Channel Coordinator
MSTV
Suite 310
1776 Massachusetts Avenue, N.W.
Washington, D.C. 20036
fax: 202-861-0342
email: vtawil@delphi.com

Victor Tawil

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: Television Station KULC

FROM: Joe Snelson, Region 3, Technical Coordinator
Telephone: 913-677-7250

RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC Database is correct for your station.

Check Here
if Correct

| | | |
|-----------------------|-----------|-------------------------------------|
| State: | UT | <input checked="" type="checkbox"/> |
| City of License: | OGDEN | <input checked="" type="checkbox"/> |
| Station Call Sign: | KULC | <input checked="" type="checkbox"/> |
| Channel: | 9 | <input checked="" type="checkbox"/> |
| Power: | 166 KW | <input checked="" type="checkbox"/> |
| Antenna Height: | 893 mtr. | <input checked="" type="checkbox"/> |
| RCAMSL: | 2600 mtr. | <input checked="" type="checkbox"/> |
| Transmitter Location: | | |
| Latitude: | 40 36 30 | <input checked="" type="checkbox"/> |
| Longitude: | 112 09 34 | <input checked="" type="checkbox"/> |
| Directional Antenna: | Yes | <input checked="" type="checkbox"/> |
| Reference Angle: | 60° | <input checked="" type="checkbox"/> |

Please provide any necessary corrections in the spaces below:

| | |
|-----------------------|-------|
| State: | _____ |
| City of License: | _____ |
| Station Call Sign: | _____ |
| Channel: | _____ |
| Power: | _____ |
| Antenna Height: | _____ |
| RCAMSL: | _____ |
| Transmitter Location: | _____ |
| Latitude: | _____ |
| Longitude: | _____ |
| Directional Antenna: | _____ |
| Reference Angle: | 60° |

PLEASE RETURN THIS FORM ONLY IF YOU HAVE CORRECTIONS BY FAX OR BY MAIL OR RESPOND VIA EMAIL NO LATER THAN OCTOBER 20, 1996 TO:

Victor Tawil
DTV Channel Coordinator
MSTV
Suite 310
1776 Massachusetts Avenue, N.W.
Washington, D.C. 20036
fax: 202-861-0342
email: vtawil@delphi.com

Salt Lake City

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: Victor
FROM: Lanny Nass, Region None
Telephone: 457-4602
RE: FCC NTSC Engineering Database

Region 3

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC NTSC Database is correct for your station:

Salt Lake City, UT

Check Here
if Correct

| | | |
|-----------------------|-------------|-------------|
| Station Call Sign: | <u>KUTV</u> | <u> </u> |
| Channel: | <u>2</u> | <u> </u> |
| Power: | <u> </u> | <u> </u> |
| Antenna Height: | <u> </u> | <u> </u> |
| RCAMSL: | <u> </u> | <u> </u> |
| Transmitter Location: | <u> </u> | <u> </u> |
| Latitude: | <u> </u> | <u> </u> |
| Longitude: | <u> </u> | <u> </u> |
| Directional Antenna: | <u> </u> | <u> </u> |
| Reference Angle: | <u> </u> | <u> </u> |

Please provide any necessary corrections in the spaces below:

| | |
|-----------------------|--------------------------------|
| Station Call Sign: | <u>KUTV</u> |
| Channel: | <u>2</u> |
| Power: | <u>45.7</u> |
| Antenna Height: | <u> </u> |
| RCAMSL: | <u>2641 2647.0m</u> |
| Transmitter Location: | <u> </u> |
| Latitude: | <u>40° 36' 23"</u> |
| Longitude: | <u>112° 9' 47"</u> |
| Directional Antenna: | <u>No</u> |
| Reference Angle: | <u> </u> |

Data used in allocation table was from a 1980
CP that was never built.

Lanny

FCC NTSC ENGINEERING DATABASE CORRECTION SHEET

TO: Television Station KRQE

FROM: Joe Snelson, Region 3, Technical Coordinator
Telephone: 913-677-7250

RE: FCC NTSC Engineering Database

In connection with the Broadcasters' campaign to evaluate and to prepare comments on the FCC's DTV allotments/assignments proposal, the Regional Coordinating Teams are verifying the accuracy of the FCC's NTSC Engineering Database. Please confirm that the following information contained in the FCC Database is correct for your station.

Check Here
if Correct

| | | |
|-----------------------|-------------|-------------------------------------|
| State: | NM | <input checked="" type="checkbox"/> |
| City of License: | ALBUQUERQUE | <input checked="" type="checkbox"/> |
| Station Call Sign: | KRQE | <input checked="" type="checkbox"/> |
| Channel: | 13 | <input type="checkbox"/> |
| Power: | 87.1 KW | <input checked="" type="checkbox"/> |
| Antenna Height: | 1287 mtr. | <input checked="" type="checkbox"/> |
| RCMSL: | 3300 mtr. | <input checked="" type="checkbox"/> |
| Transmitter Location: | | |
| Latitude: | 35 12 40 | <input checked="" type="checkbox"/> |
| Longitude: | 106 26 57 | <input checked="" type="checkbox"/> |
| Directional Antenna: | No | <input checked="" type="checkbox"/> |
| Reference Angle: | _____ | <input checked="" type="checkbox"/> |

Please provide any necessary corrections in the spaces below:

| | |
|-----------------------|-------|
| State: | _____ |
| City of License: | _____ |
| Station Call Sign: | _____ |
| Channel: | 13 + |
| Power: | _____ |
| Antenna Height: | _____ |
| RCMSL: | _____ |
| Transmitter Location: | _____ |
| Latitude: | _____ |
| Longitude: | _____ |
| Directional Antenna: | _____ |
| Reference Angle: | _____ |

PLEASE RETURN THIS FORM ONLY IF YOU HAVE CORRECTIONS BY FAX OR BY MAIL OR RESPOND VIA EMAIL NO LATER THAN OCTOBER 20, 1996 TO:

Victor Tawil
DTV Channel Coordinator
MSTV
Suite 310
1776 Massachusetts Avenue, N.W.
Washington, D.C. 20036
fax: 202-861-0342
email: vtawil@delphi.com